

Oil Field Environmental Incident Summary

Incident: 20140912132944 **Date/Time of Notice:** 09/12/2014 13:29
Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Name: SHAFERMAKER 11-15MBH-ULW
Field Name: ELIDAH **Well File #:** 27584
Date Incident: 9/11/2014 **Time Incident:** 17:40 **Facility ID Number:**
County: MCKENZIE **Twp:** 151 **Rng:** 97 **Sec:** 15 **Qtr:**
Location Description:

Submitted By: Tim Homiston **Received By:**
Contact Person: Tim Homiston
PO BOX 51810
MIDLAND, TX 79710-1810

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	3	Barrels	1	Barrels		
Other						

Description of Other Released Contaminant:

Inspected: **Written Report Received:** **Clean Up Concluded:**

Risk Evaluation:

No immediate risk, residual water vacuumed up and soil will be remmediated when tank is moved

Areal Extent:

Area on-site within dike of about 8' X 8'

Potential Environmental Impacts:

None

Action Taken or Planned:

Leaking valve was closed and plug tightend on tank. All other tanks were inspected to make sure valves were fully closed and plug tight. Residual fluid vacuumed up and soil will be remmediated when tanks are moved off site

Wastes Disposal Location: Residual fluid was hauled to disposal and remmediated soil will be hauled to Indian Hills disposal site

Agencies Involved:

Updates

Date: 9/12/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.